

FIG. 1





FIG. 2



3 / 12

## FIG. 3

$$H = \begin{pmatrix} R(1,1) & \dots & R(1,K) \\ \dots & \dots & \dots \\ R(J,1) & \dots & R(J,K) \end{pmatrix}$$

301

$$R(j,k) = Q(j,k) \otimes P(j,k)$$

302

FIG. 4




FIG. 5






FIG. 6




**FIG. 7**



8 / 12

**FIG. 8**



**FIG. 9A**

$$(Q(j, k)) = \begin{pmatrix} 1 & 0 & 0 & 1 & 1 & 0 \\ 0 & 1 & 1 & 0 & 0 & 1 \\ 0 & 1 & 1 & 0 & 0 & 1 \\ 1 & 0 & 0 & 1 & 1 & 0 \end{pmatrix} \quad 901$$

$$(P(j, k)) = \begin{pmatrix} 0 & 0 & 1 & 1 & 0 & 0 & 1 & 0 \\ 0 & 1 & 0 & 0 & 1 & 0 & 0 & 1 \\ 1 & 0 & 0 & 0 & 0 & 1 & 1 & 0 \\ 0 & 0 & 1 & 0 & 1 & 0 & 1 & 0 \\ 1 & 0 & 0 & 0 & 1 & 0 & 0 & 1 \\ 0 & 1 & 0 & 1 & 0 & 0 & 1 & 0 \end{pmatrix} \quad 902$$

**FIG. 9C**

$$H = (R(j, k)) = (Q(j, k) \otimes P(j, k)) =$$

$$\left( \begin{array}{c|c|c} 0 & 0 & 1 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 \\ 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ \hline 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 \\ \hline 0 & 1 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 & 0 & 1 & 0 & 0 \end{array} \right) \quad 903$$

FIG. 10A





FIG. 11

c (1)	c (2)	c (3)	c (4)	r + c (1) + c (2) +c (3) + c (4)
-------	-------	-------	-------	-------------------------------------

FIG. 12



**FIG. 13**


$$\left( \begin{array}{ccccccccc} P & P & 0 & 0 & 0 & 0 & P & P & P \\ P & P & P & P & P & 0 & 0 & 0 & P \\ P & P & P & P & 0 & P & 0 & 0 & P \\ P & P & P & 0 & P & P & 0 & P & 0 \\ P & P & 0 & P & P & P & P & 0 & 0 \end{array} \right)$$

**FIG. 14A**  
 PRIOR ART

$$H = \begin{pmatrix} 1 & 2 & 3 & 4 & 5 & 6 & 7 & 8 \\ 1 & 0 & 0 & 1 & 0 & 1 & 1 & 1 \\ 0 & 1 & 1 & 1 & 0 & 1 & 0 & 1 \\ 1 & 1 & 0 & 1 & 1 & 1 & 0 & 0 \\ 1 & 0 & 1 & 0 & 1 & 0 & 1 & 1 \end{pmatrix} \begin{matrix} 1 \\ 2 \\ 3 \\ 4 \\ 5 \\ 6 \\ 7 \\ 8 \end{matrix}$$

PARTY CHECK MATRIX H

**FIG. 14B**  
 PRIOR ART



TANNER GRAPH G

12 / 12

FIG. 15  
PRIOR ART

